Radioddity

CPS for DB50

V1.0.1, July 12th, 2024

CPS Release notes

The following table lists the details that had been changed with new versions of the CPS.

CPS software 1.0.1 as of July 12th, 2024

revision	Changes	released
CPS V1.0.1	• Minor non functional corrections	2024-07-12

Initial CPS software

revision	Changes	released
CPS 1.0.0	This has been the initial release	2024-06-05

We would like to thank all Radioddity customers for their constructive feedback.

If you do find any bug in the radio's firmware, our CPS, this documentation or if you are missing a feature, you would have expected, write an email to support@radioddity.com. In general, the software- and firmware-updates for your Radioddity DB50 are free of charge. Using a CPS or a firmware not originating from Radioddity may void your warranty.

Thank You for Shopping at Radioddity!
FIND TUTORIALS, SUPPORT AND MORE AT:

https://www.radioddity.com/

https://www.facebook.com/radioddity

https://www.youtube.com/c/Radioddityradio