



Release Notes for
DB40-D firmware
959E.E6T.EBPSAB.007 (A)
B49C.E6T.EORNAB.006 (B)
as of 2024-06-07

June 20th, 2024

Release notes

The following table lists the details that had been changed with new versions of the firmware.

**Please read these complete release notes
before starting to update your Radioddity DB40-D.**

Attention: *Never update your radio unless it is really required or with other words*

Don't fix it, if it isn't broken!

This cannot be stressed often enough. Only take those firmware as found on our support pages. Before performing an update, double check that the firmware on our support page has not been withdrawn.

DB40-D firmware as of June 20th, 2024

revision	Changes	released
959E.E6T.EBPSAB.007 Jun 7 2024 10.18.37 (A)	<ul style="list-style-type: none">Decreased the number of predefined QuickMsgs to 16Added additional encryption options, including AES256*At least DRS CPS_V3.3 CPS 9.2.28 is required to edit the codeplug	2024-06-20
B49C.E6T.EORNAB.006 Jun 7 2024 11.06.56 (B)		

*) **Using encryption is not allowed In Amateur radio networks.**

DB40-D initial firmware as of August 26th, 2023

revision	Changes	released
959E.E6T.EBPSAB.007 Aug 26 2023 14.42.52 (A)	This has been the initial release	2023-08-26
B49C.E6T.EORNAB.006 Aug 26 2023 14.35.04 (B)		

We would like to thank all Radioddity DB40-D customers for their constructive feedback.

If you do find any bug in the radio's firmware, our CPS, this documentation or if you are missing a feature, you would have expected, write an email to support@radioddity.com. In general, the software- and firmware-updates for your Radioddity DB25-D, DB40-D and Radioddity GD-88 are free of charge. Using a CPS or a firmware not originating from Radioddity may void your warranty.



Thank You for Shopping at Radioddity!

FIND TUTORIALS, SUPPORT AND MORE AT:



<https://www.radioddity.com/>



<https://www.facebook.com/radioddity>



<https://www.youtube.com/c/Radioddityradio>